

Advantage Aviation Technologies

American Eurocopter
Oil Tank/
Hydraulic Tank
Leak Repair and
Refurbishment



Advantage Aviation Technologies specializes in aircraft welding repairs, aircraft overhauls, and engineering repairs for aircraft components and subcomponents.

Part Numbers:

366A75-3019-01, 366A75-3380-01
703A53-01360-1801, 703A53-000-004
365A52-1360-1801, 365A531360-1151
365A53-1360-1602, 365A53-8013-01
365A53-8013-03, 365A75-2960-00
365A75-2966-00, 365A75-4017-00
365A75-4023-00, 117-67171-02
117-67172-02, 350A75-1010-0001
350A75-4005-02, 355A75-1330-03
355A75-1330-04703A53-0000-01



3213 North Main
Cleburne, Texas 76033
Local: 817-558-4942
Fax: 817-556-9034
info@aatinc.net
www.aatinc.net

Due to extreme conditions and wear, these tanks suffer cracks, dents and disfigurement.

AAT repairs this damage with state of the art welding techniques and patented procedures that not only repair this damage and cracks but also deter further cracking in the repaired areas.

As these parts are received, the tanks are cleaned and pressure tested. After this, the dents are removed and any disfigurement is corrected. All cracks are repaired and sight glasses are Pro Sealed. Tanks are then repressure tested to ensure it meets our high standards. The part is then Alodine coated to prevent future corrosion.

Normal repairs have 5 Day turn around. AOG Service is available next day in most cases, if necessary